System 76 Pangolin suspend

To fix the suspend issue that is present due to the EC sending wake signals. The following needs to be added

```
sudo rpm-ostree kargs --append='acpi.ec_no_wakeup=1'
```

Revision #3
Created 2026-11-11 15:38:55 UTC by Kory
Updated 2026-11-11 15:41:08 UTC by Kory